



# King Greenleaf RC Lead in Water Test Results

## FY21 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012000	3/23/2021	3/23/2022	Ground Floor	Cooler	In hallway adjacent to janitors' closet	Low	Left	WF-03232021-012000	4/7/2021	FT-FY21-032021-012000-A	<1	FT-FY21-032021-012000-B	<1
WS- 012001	3/23/2021	3/23/2022	Ground Floor	Cooler	In hallway adjacent to janitors' closet	High	Right	WF-03232021-012001	4/7/2021	FT-FY21-032021-012001-A	<1	FT-FY21-032021-012001-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012002	2/4/2021	2/4/2022	Ground Floor	Food Prep Sink	In kitchen	WF-02042021-012002	4/7/2021	FT-FY21-032021-012002-A	<1	FT-FY21-032021-012002-B	<1